

Product Data Sheet

Product	Galvanised Iron Cleaner
Product Code	518
Description	This product is a clear solution containing solvents, detergents, emulsifiers and acidic material

Use

Apply to new galvanized iron by using a coarse cloth (orange woven bag) and rub on to surfaces applying moderate pressure. Allow the material to remain on the surface for 10 – 20 minutes and then rinse with clean running water. The galvanized iron surface should now exhibit lower brightness and have a dull metallic lustre. If the surface is still shiny, then the wax coating has not been removed completely. Repeat the above procedure until the surface has a dull metallic lustre.

Painting

Allow the surface to dry before painting with the specified materials.

Precautions

- Use eye shield and rubber gloves
- In case of skin or eye contact, immediately rinse affected area with clean water
- Do not smoke or expose the product to naked flames

Flashpoint	12°C
Toxicity	normal when used in well ventilated areas

Note

THIS PRODUCT IS LEAD FREE

No guarantee is implied by the recommendations contained herein since the data sheet is issued for information purposes only. Method of application on surface, cleanliness and conditions of use etc. are beyond our control.